FS Check In Meeting Agenda

Wednesday, December 14th, 2010, 9:00 AM – 5:00 PM Sheraton Airport Hotel, 8234 NE Airport Way, Cascade A and B Conference Line Non-Responsive

9:00 – 10:30	01. Preliminary Capping Chemical Isolation Evaluation Presentation
10:30 - 12:00	02. Preliminary Methods for Volume Determinations
12:00 – 1:00	Break for Lunch
1:00 – 2:30	03. Disposal Site Screening Evaluation
2:30 – 4:00	04. Sensitivity/Uncertainty Analyses and Other Evaluations to Support SMA Refinement
4:00 - 5:00	Discussion Major Issues and Process Path Forward
	A. Initial EPA Feedback Regarding the Level of Detail Provided in Today's Presentations

B. List of Additional Key Topics for Future Presentations

Do Not Quote or Cite

This document is currently under review by US EPA and its federal, state and tribal partners, and is subject to change in whole or part